

OSAKA OPC 50033 IMPULSE SOMUN SÖKME 3/8

No.	Part No.	Description	Q'ty	FİYAT		Part No.	Description	Q'ty	FİYAT	
				No.					No.	
1	I100-410	Greasing Screw	1	\$ 1,20	45	00-41135	O-Ring	1	\$ 1,20	
2	00-4153	O-Ring	1	\$ 1,20	46	IS40-307	Rear Cover	1	\$ 10,80	
3	I60S-201	Pulse Unit Housing	1	\$ 64,80	47	IS40-524	Valve Seat	1	\$ 58,80	
4	I40S-202	Bushing	1	\$ 22,80	48	00-41145	O-Ring	2	\$ 1,20	
5	I40S-424	Washer	1	\$ 1,80	49	IS40S-312	Washer	1	\$ 12,00	
6	I60S-401	Pulse Cylinder Seat	1	\$ 46,80	50	00-3824	Steel Ball	1	\$ 1,20	
7	I70-410	Greasing Screw	1	\$ 3,00	51	IS40S-313	Spring	1	\$ 1,80	
8	00-41113	O-Ring	4	\$ 1,20	52	IS40S-311	Valve	1	\$ 12,00	
9	00-3318	Spring Pin	2	\$ 1,20	53	IS40-518	Seat	1	\$ 16,80	
10	00-41127	O-Ring	2	\$ 1,20	54	IS60-101	Motor Housing (incl.55)	1	\$ 300,00	
11F	I40S-403-B	Front Cover	1	\$ 40,80	55	I40S-108	Bushing	4	\$ 0,00	
12	00-2602	X-Ring	1	\$ 19,20	56	IS100-609	Screw	1	\$ 4,80	
13	I40S-411	Valve Screw	1	\$ 3,60	57	I40S-102	Hanger	1	\$ 12,00	
14	00-3435	Pin	2	\$ 1,80	58	00-41146	O-Ring	1	\$ 1,20	
15	I40S-408	Front Plate	1	\$ 49,20	59	00-4169	O-Ring	1	\$ 1,20	
16	IS60S-405	Anvil	1	\$ 126,00	60	I40-104	Nut	1	\$ 12,00	
17B	I60S-406-B	Drive Blade	2	\$ 85,20	61	I40-504	Trigger	1	\$ 1,80	
18B	I60S-452	Roller	2	\$ 10,80	62	00-3354	Spring Pin	1	\$ 1,20	
19	I40S-407	Spring	2	\$ 3,60	63	00-0505	Screw	2	\$ 1,20	
20B	IS40-450	Block Valve	1	\$ 12,00	64	I100-503	Regulator Knob	1	\$ 18,00	
21F	IS60S-412-C	Valve	1	\$ 16,80	65	00-4101	O-Ring	1	\$ 1,20	
22	00-41130	O-Ring	1	\$ 1,20	66	IS40-505	Valve Stem	1	\$ 7,20	
23	00-3813	Steel Ball	2	\$ 1,20	67	I100-508	Bushing	1	\$ 7,20	
24F	IS60S-425-C	Spring	1	\$ 1,80	68	00-41172	O-Ring	1	\$ 1,20	
25C	I60S-404-B	Pulse Cylinder	1	\$ 267,60	69	I40-507	Spring	1	\$ 1,80	
26	00-3436	Pin	1	\$ 1,80	70	I100-506	Spring	1	\$ 1,80	
27	00-3407	Pin	2	\$ 1,20	71	IS40-502	F/R Valve	1	\$ 34,80	
28F	IS40S-415-C	Rear Plate	1	\$ 132,00	72	I40-501	Valve Sleeve	1	\$ 28,80	
29C	00-41173	O-Ring	2	\$ 1,20	73	00-41111	O-Ring	2	\$ 1,20	
30C	IS40S-421	Pressure Valve	2	\$ 13,20	74	I40-601	Muffler	1	\$ 6,00	
31	IS60-314	Shut Off Stem	1	\$ 14,40	75	I40-603	Exhaust Deflector	1	\$ 15,60	
32	IS40S-317	Spring	1	\$ 1,80		I40-604A	Air Inlet 1/4"-19PF		\$ 0,00	
33	I40S-423	Washer	1	\$ 1,20		I40-604B	Air Inlet 1/4"-19PT	1	\$ 37,20	
34	I40S-402	Lock Nut	1	\$ 13,20		I40-604C	Air Inlet 1/4"-18NPT		\$ 0,00	
35	I40S-306	Lock Nut	1	\$ 36,00	77	I100-511	Pin	1	\$ 2,40	
36	00-2348	Ball Bearing	1	\$ 36,00	78C	I60S-453	Spring	1	\$ 1,80	
37	00-3324	Spring Pin	1	\$ 1,20	79C	I40S-454	Block Cap	1	\$ 3,60	
38	I60-302	Cylinder	1	\$ 186,00	80F	I40-409	Back Up Ring	1	\$ 3,60	
39	00-3356	Spring Pin	2	\$ 1,20					\$ 0,00	
40	I60S-303	Rotor	1	\$ 84,00	※	IS60RK	Repair kit :Index No-		\$ 36,00	
41	I60S-304	Rotor Blade	9	\$ 4,80			8(2); 10(2) ; 12; 19(2); 29C(2);80F		\$ 0,00	
42	I40-305	Rear Plate	1	\$ 63,60	※	IS60SK	Service kit :Index No-		\$ 546,00	
43	00-2356	Ball Bearing	1	\$ 19,20			15;16;17B(2);18B(2);28F;41(9);51		\$ 0,00	
				\$ 0,00			67;68;69		\$ 0,00	
44	00-41144	O-Ring	2	\$ 1,20	※	I40S-451	Impulse Oil(100c.c)		\$ 76,80	

êPulse unit includes: Index No :

6,7,8,9,10,11F,12,13,14,15,16,17B,18B,19,20B,21F, 22, 23, 24F,25C,26,27,28F,29C,30C,34,78C,79C,80F

OSAKA OPC 50033 IMPULSE SOMUN SÖKME 3/8



